

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	Mark Reynolds Resident Agent	
OGM	Pete Hess Environmental Scientist III	

Inspection Report

Permit Number:	C0150025
Inspection Type:	COMPLETE
Inspection Date:	Friday, February 08, 2008
Start Date/Time:	2/8/2008 9:00:00 AM
End Date/Time:	2/8/2008 10:40:00 AM
Last Inspection:	Tuesday, January 08, 2008

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Clear; temrperature in 20's F.</u> InspectionID Report Number: <u>1545</u>

Accepted by: dhaddock

3/5/2008

Permitee: CO-OP MINING CO
Operator: CO-OP MINING CO

Site: BEAR CANYON MINE

Address: PO BOX 1245, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership Types of C	Operations
------------------------------	------------

10,967.39	Total Permitted	✓ Federal	✓ Underground
40.46	Total Disturbed	☐ State	Surface
	Phase I	☐ County	☐ Loadout
	Phase II	✓ Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on December 17, 2007 that the third quarter 2007 surface and ground water monitoring information for the Bear Canyon permit area was in the Division's electronic data base pipeline acceptable for uploading. The Permittee is current relative to this water monitoring requirement contained as Attachment "A" of the current State permit.

There are no pending compliance actions for this site.

There are approximately 24 to 30 inches of snow pack at the site.

The Permittee has retreated approximately two-thirds of the length of the first long wall panel in the Tank seam of the new Federal lease addition. The first eagle nest to be undermined will occur in Panel #2. A golden eagle mitigation plan (Task ID # 2876) was approved by the Division on November 28, 2007.

Inspector's Signature:

Date

Wednesday, February 13, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0150025 Inspection Type: COMPLETE

Inspection Date: Friday, February 08, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark			
2.	Signs and Markers	V			
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V		✓	
4.d	Hydrologic Balance: Water Monitoring	V		✓	
4.e	Hydrologic Balance: Effluent Limitations	V		V	
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control	✓			
15.	Cessation of Operations		V		
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.t	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		V	
22.	Other				

Permit Number: C0150025 Inspection Type: COMPLETE

Inspection Date: Friday, February 08, 2008

Page 3 of 3

3. Topsoil

All topsoil piles at the site are snow covered.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Mr. Mark Reynolds, P.E., conducted the fourth quarter of 2007 impoundment inspections for catch basin 1, 2, and 3, as well as sediment ponds A, B, C, and D on December 15, 2007. All seven impoundments were snow covered. The inspection reports indicate that all slopes / embankments associated with the impoundments appeared stable, with no indication of structural instability. Ponds A, C, and D received P.E. certifications.

4.c Hydrologic Balance: Other Sediment Control Measures

All other methods used for sediment control are under snow.

4.d Hydrologic Balance: Water Monitoring

Bear Creek is frozen and snow covered. Flow was not audible.

4.e Hydrologic Balance: Effluent Limitations

The Permittee sent the Utah DWQ a UPDES renewal application on December 15, 2007. There have not been any recent parameter exceedances at this site.

21. Bonding and Insurance

The Permittee provided general liability insurance renewal information to the Division on January 2, 2008. Renewed coverage will remain in effect until January 1, 2009. Coverage amounts are adequate; coverage is provided for damage incurred from the use of explosives.